

## Inspector

### Description of Tasks:

1. Read and utilize all measuring instruments common to our operations, such as rules, squares, circumference tapes, vernier tapes, vernier calipers, depth and diameter gauges, radius gauges, vide-gauge, pressure gauges, etc., with minimum supervision.
2. Apply proper testing procedures for water or air pressure testing setups.
3. Check all dimensions on spun, machined, welded, forged, cast parts, etc., and make necessary reports on the inspection copy of the work order. Assist operator or supervisor in arriving at quality standards required and make suggestions and recommendations whenever possible.
4. Assume responsibility for stopping operations on parts produced that are not within tolerances or quality standards, and report at once to the supervisor and general supervisor if necessary to the worker's superior as well.
5. Inspect and determine responsibility regarding returned merchandise by the customer and fill out necessary papers outlining the item in question.
6. Note and report all instances of careless handling of material and defective workmanship. Always strive through cooperation with supervisors and other employees to eliminate such conditions.
7. Make inspections and report all defects on incoming materials, tools, dies, casting, etc. as assigned by the supervisor, and perform all inspections and related functions.
8. Permit no materials to be shipped when known to be substandard. Make out release papers when parts have been cleared for shipment.
9. Devise simple checking setups and simple fixtures for fast checking of parts.
10. Always maintain the inspection department in neat and orderly condition and exercise proper practices in the care of all equipment.
11. Cooperate with management in observance of procedures and maintaining records required. These may be in accordance with MIL-Q-9858, or to any other specification that Spincraft must conform to.
12. Performs other duties as required to complete other tasks.

### TOOLS/EQUIPMENT USED

- Calipers
- Precision Knees
- Computer
- Hand Tools

### PROTECTIVE DEVICES/CLOTHING REQUIRED

Safety shoes, safety glasses, gloves. Hearing protection is required during some operations with machines cutting parts.

### EDUCATION/TRAINING REQUIREMENTS

High School diploma or G.E.D. along with trade school or experience in lieu of all types of machining methods at Spincraft, MA, as detailed in the job description, and the ability to read and write English.

**ENVIRONMENTAL CONDITIONS**

Ambient temperature 85% of the workday.

\*\*Experience or formal training/schooling is a plus, but we will train the right candidate.

**Job Type:** Full-time

**Pay:** \$25.16 - \$30.91 per hour

**Benefits:**

- Dental Insurance
- Employee assistance program
- Employee discount
- Flexible spending account
- Health insurance
- Life insurance
- Paid time off
- Professional development assistance
- Referral program
- Retirement plan
- Tuition reimbursement
- Vision insurance

**Schedule:**

- 8-hour shift

**Work Location:** In person